

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2617	DATE	March 16, 2018
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The fuel supply hose on engine side may contact with an engine mounting and engine mounting screw due to wrong design. This contact may create a wearing which could eventually lead to a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KWH5F	「KANGOO」	2013-2016	1,612
ABA-KWH5F1		2016-2017	1,781
		TOTAL	3,393