

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2626	Date	March, 23, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>Rear lamp operation on vehicles should be consistent with the component certification described operation to comply with Japanese Automobile Type Approval regulations. The rear lamp system installed on certain Land Rover Range Rover Velar vehicles fails to operate in the manner described on the component certification.</p> <p>It has been identified on already imported Land Rover Range Rover Velar 2018MY vehicles that the rear lamp system does not conform to the component level certified condition and therefore, does not meet the requirements of Article 39 of Japanese Type Approval Regulations.</p> <p>On vehicles in Japan during daylight hours, the tailgate lamp is not illuminated and as such the stop lamp fails to meet the Inboard Visibility Angle Requirements.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-LY3VA	「Range Rover Velar」	2018	140
LDA-LY2NA	「Range Rover Velar」	2018	241
Total			381