

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 2 2 3	DATE	M a r . 2 7 . 2 0 1 8
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to the inappropriate manufacturing of the primary driven gear in the motor, some of the surfaces of the said gear teeth were found to be not machined smoothly. Because of that, the noise which is generated during acceleration may not conform to the requirements in Regulation No. 41.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RH07J	MT320	2017	36
		TOTAL	36