

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4222	DATE	March 28,2018
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	<p>Due to the strength poverty of the fenders for 3rd and 4th axles regarding the 4 axle container carrier, there is possibility that cracks may occur on the top fender mounting part due to vibration during traveling.</p> <p>Therefore, if the vehicle is used continuously in that condition, the top fender drops off and it may obstruct the other traffic.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CYJ51W5	GIGA	2004~2005	5
PJ-CYJ51W6	GIGA	2005~2006	4
PJ-CYJ77W6	GIGA	2007	2
PKG-CYJ77W8	GIGA	2008	1
PDG-CYJ77W8	GIGA	2010	1
LKG-CYJ77AA	GIGA	2012	1
QKG-CYJ77AA	GIGA	2012~2016	50
QKG-CYJ77BA	GIGA	2016~2017	77
QPG-CYJ77BA	GIGA	2016~2017	12
BDG-FW1EXYJ	HINO PROFIA	2010	1
BDG-FW1EZYJ	HINO PROFIA	2008	2
QKG-FW1EXBJ	HINO PROFIA	2013	1
QKG-FW1EXEJ	HINO PROFIA	2014	2
QPG-FW1EXEJ	HINO PROFIA	2016~2017	10
		TOTAL	169