

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4216	DATE	Mar . 29 , 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-YA5	「EXIGA」	2013	239
DBA-YAM		2013	4,187
		TOTAL	4,426