

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 2 3 5	DATE	Mar.29.2018
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In vacuum pump of diesel engine, because the durability of the oil hose is insufficient, the deformation by the pressure fluctuation of the oil is repeated, and the hose may be cracked. For the reason, engine oil leaks and warning light turns on, if the vehicle continues to be driven in this condition, in an extreme case, the engine becomes poor in lubrication, and the engine might stop during a run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LDF-VW2E26	NV350 CARAVAN	2012 ~ 2015	17,977
LDF-VW6E26			13,204
LDF-CW4E26			1,831
LDF-CW8E26			4,048
LDF-DW4E26			325
LDF-JVW2E26	ISUZU COMO		484
LDF-JVW6E26			386
LDF-JCW4E26			49
LDF-JCW8E26			49
LDF-JDW4E26			5
		TOTAL	38,358