

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2607	DATE	30 March, 2018
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Fine hairline cracks can occur on the filter flange of the fuel pump on the affected vehicles. As a result, fuel can seep out causing a smell of fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-9PABFD	Cayenne	2004	284
		2005	486
		2006	560
GH-9PABFDA		2004	37
		2005	31
		2006	41
GH-9PA00	Cayenne S	2003	190
		2004	296
		2005	227
		2006	286
GH-9PA00A		2003	8
		2004	92
		2005	69
		2006	63
GH-9PA50A	Cayenne Turbo	2003	84
		2004	340
		2005	219
		2006	257
	Cayenne Turbo S	2006	31
		TOTAL	3601