

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2639	DATE	30/03/2018
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive ASIA Pte Ltd)		
DESCRIPTION OF DEFECT	Activation of a non-desiccated ammonium nitrate inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed on passenger side air bag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MP4-12C	「McLaren MP4-12C」	2013, 2014	35
ABA-MP4-12CS	「McLaren MP4-12C Spider」	2013, 2014	70
ABA-MP4-12CP	「McLaren 650S」	2015	2
ABA-MP4-12CSP	「McLaren 650S Spider」	2015	6
		TOTAL	113