

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2640	DATE	30/03/2018
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive ASIA Pte Ltd)		
DESCRIPTION OF DEFECT	Activation of a non-desiccated ammonium nitrate inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed on passenger side air bag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	「McLaren P1」	2014, 2015	32
		TOTAL	113