

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4240	DATE	Apr.11.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the manual parking brake lever of the subject vehicles, which contains a spring and gears to hold lever position, due to insufficient spring force, if the gears balance at the tooth tips of each gears when the lever is pulled up, there is a possibility that the tooth tips could become out of balance due to vibration causing the lever to be released. If this were to occur, the braking force of the parking brake could be reduced and, in the worst case, the parked vehicle could roll away.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADF-KDY221 LDF-KDY221 QDF-KDY221	[DYNA] [TOYOACE]	2007-2016	2,523
ADF-KDY231 LDF-KDY231 QDF-KDY231			19,659
ADF-KDY241V LDF-KDY241V			338
ADF-KDY281 LDF-KDY281			3,331
ABF-TRY220			3,195
ABF-TRY230			11,675
NBG-TRY231			1,161
NBG-TRY281			194
		TOTAL	42,076