## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIGN No.	GAI-2638	DATE	April 13, 2018	
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)			
DESCRIPTION OF DEFECT	As a result of a defective weld joint on the gas generator, the passenger airbag may not be filled with the required volume of gas if the airbag is deployed in an accident. The ability of the airbag to protect the passenger could be compromised as a result.  The airbag unit for the passenger airbag must be replaced on the affected vehicles.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8UCZD	Q3 1.4	2017	3
ABA-8UCZGF	RSQ3	2017	3
		Total	6