

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2645	Date	April. 17, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>Jaguar Land Rover has received Electronic Product Quality Reports (EPQRs) from dealers stating that on certain 2016, 2017 and 2018 MY Jaguar XF, XJ, XE and F-PACE vehicles the Thin Film Transistor (TFT) Instrument Cluster (IC) has been going blank intermittently. The instrument cluster will not display anything in this condition but will reset whilst driving. As such, these vehicles fail to comply with your National Regulations or United Nations Economic Commission for Europe (ECE) Regulation number 121-01 for a short period of time.</p> <p>Without the instrument cluster displaying important information such as the vehicle's speed, there would be an increased risk of a crash.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-DC3VA	「F-PACE」	2017-2018	134
CBA-J128B	「XJ Lux.」 「XJ Premium. Lux.」	2016-2017	111
CBA-J12MA	「XJR」	2017	9
CBA-J12PB	「XJ Lux.」	2017	11
CBA-J24MA	「XJ SuperSport LWB」	2017	12
CBA-JA2XB	「XE 250PS」 「XE 200PS」	2018	75
CBA-JB2GA	「XF」	2017	122
CBA-JB2XB	「XF 250PS」 「XF 200PS」	2018	2
CBA-JB3VA	「XF」	2017-2018	19
LDA-DC2NA	「F-PACE」	2017	631
LDA-JA2NA	「XE」	2018	162
LDA-JB2NA	「XF」	2017-2018	80
Total			1368