

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4239	DATE	April 18, 2018
MANUFACTURER	KYB Corporation 4-1, Hamamatsu-cho 2-chome, Minato-ku, Tokyo, Japan		
DESCRIPTION OF DEFECT	Some of the lighting device of a concrete mixer truck, there are which are installed incorrectly on the left and right because the installation instructions of the rear combination lamp are inappropriate. Therefore, the position of the water drain hole is inverted upside down, draining is not appropriately performed, and the lamp may not be lighted. Also, the lighting part of the tail light may be different from the design state and not conform to the safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CW5AL	QUON	2017	15
TOTAL			15

(日本工業規格A列4番)