

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4249	DATE	Apr. 19. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>① On certain heavy-duty buses, because the console for the parking brake lever is fixed improperly, if something is put between the console concerned and the driver's seat partition, the console may move, causing the parking brake lever and the console to interfere. Therefore, if the parking brake lever is pulled up, it may be retained before it is properly locked. In the worst case, the lever may be released by the engine vibration etc., resulting the vehicle to start moving.</p> <p>② On certain heavy and middle-duty buses, because the fixing structure of the plug on the engine intake pipe is improper, the plug concerned may come out by the internal pressure in high load driving, resulting the engine output to lower while driving and the plug to drop on the road.</p> <p>③ On certain heavy-duty buses, because the VSC (Vehicle Stability Control) off switch identification display is improper, these vehicles fail to conform to Agreement of Regulation number 121.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-RU1ESBA	[HINO SELEGA]	2014~2017	1,278
QRG-RU1ESBA			
2RG-RU1ESDA		2017~2018	219
LDG-RU8JHBA		2014~2017	467
SDG-RU8JHBA			
QQG-RU1ASBR		2014~2017	22
QRG-RU1ASCA		2014~2017	2,030
QTG-RU1ASCA			
2TG-RU1ASDA		2017~2018	294
2DG-RU2AHDA		2017~2018	83
2KG-RU2AHDA			
2DG-RR2AJDA	[HINO Melpha]	2017	34
		TOTAL	4,427