VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No.4241DATEApril 20 ,2018MANUFACTURERNIPPON TREX CO., LTD.
350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, JapanDESCRIPTION OF
DEFECT4axle container carrier
Rotating part protrudes outward more than the front fender because of the
shape of 2nd, 3rd, and 4th axles are inadequate. Therefore, it does not fit into
a Safety Regulations Article18.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTES
PJ-CYJ51W5	GIGA	2004	1	
		TOTAL	1	