

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4248	DATE	April 20,2018
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	Regarding the travelling equipment of the truck mounted aerial working platform, the reinforcement plate for the base plate of the boom rest mounting may come in contact with the right rear wheel tire when the truck body is slanted, because the contact evaluation of the range of tire movement was insufficient. Therefore the tire might be damaged when such contacts are carried out repeatedly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FEA50	FUSO CANTER	2013 - 2016	27
TPG-FEA50	FUSO CANTER	2016 - 2018	187
TKG-FEA5W	ATLAS	2014	1
TRG-FEA5W	ATLAS	2016 - 2018	2
TOTAL			217