

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2652	DATE	April 25, 2018
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, the orientation of the starter supply lug might be non-compliant. Contact with a nearby metal part could cause a short-circuit. The operation involves checking the orientation of the lug / the cable, and rectifying it if necessary.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-P84AH01	PEUGEOT 3008	2016	1
LDA-T9AH01	PEUGEOT 308	2016-2017	358
LDA-T9WAH01		2015-2017	292
LDA-W2AH02	PEUGEOT 508	2015-2016	21
LDA-W2WAH02		2015-2016	12
LDA-B7CAH02	CITROEN DS4	2016-2017	174
LDA-B8AH02	CITROEN DS5	2016	6
		TOTAL	864