

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4257	DATE	Apr. 25. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy-duty trucks, due to the improper assembly of the front brake air tube, the tube may not be fully covered by the exhaust heat insulator, causing the tube to be affected by the exhaust heat directly. Therefore, the tube concerned may be melt by the exhaust heat and the air may leak, resulting the braking force to decline.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FN1AJA	[HINO PROFIA]	2017~2018	273
2KG-FN1AJG			
2PG-FN1AJA			
2PG-FN1AJG			
		TOTAL	273