

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4251	DATE	April 26 ,2018
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the wheeled system of the container semi-trailer, some are assembled to the wheel with water in the tire because of some of the inappropriate tire assembly work instructions. Therefore, if it continuously used as it is, rust may occur in the wheel and the air valve, and in the worst case, there is a risk of air leakage from the air valve.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NCCTB24082	—	2017	8
NCCTB32082	—	2016~2017	18
NCCTB34081	—	2016~2017	31
TOTAL			57