

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4246	DATE	April 27 .2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	At hydraulic circuit of agricultural tractor, the hose clamp at suction filter hose is inappropriately, some hoses are excessively deformed and cracks. Operating with that condition, the crack of hose may progress by engine vibration and oil may be leaked. In the worst case, there is a possibility that it cannot drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「YT490」	2016	247
	「YT5101」	2016	22
	「YT5113」	2016	230
-	「YT5113」	2016	96
TOTAL			595