## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-2642	DATE	14th May 2018	
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)			
DESCRIPTION OF DEFECT	The software to monitor the wear of the carbo-ceramic brake discs did not function properly due to a software bug. The estimated wear of the brake discs was reset, in very rare conditions. The risk is to reach the critical threshold without the warning lamp and message are shown to the driver. If such condition happens, the worst case scenario could be the damage of brake discs with increased risk of an accident.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F142B	488GTB	2015	9
		TOTAL	9