

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2657	DATE	May 16, 2018
MANUFACTURE	Aston Martin Lagonda Limited		
DESCRIPTION OF DEFECT	Aston martin has determined that on certain DB11 vehicles an electrostatic discharge when combined with a damaged steering column module clock spring and an insufficient grounding of the Steering Column Upper may lead to an inadvertent deployment of the driver airbag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AM501	DB11	2015-2017	217
		TOTAL	217