

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2659	Date	May, 18, 2018
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>The brazing of the fuel rail end caps is inconsistent and may not provide the design condition so not sealing the fuel rail ends. Fuel vapour and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.</p> <p>Fuel odour may be noticed by the driver and they may also observe liquid fuel if the bonnet is lifted.</p> <p>Should leaking fuel come into contact with a sufficiently hot surface there is an increased risk of fire.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
DBA-DF2XA	「E-PACE」	2018	63
DBA-DC2XB	「F-PACE」	2018	2
CBA-JA2XB	「XE 250PS」 「XE 200PS」	2018	88
CBA-JB2XB	「XF 250PS」 「XF 200PS」	2018	12
DBA-JA2XC	「XE 300PS」 「XE 250PS」 「XE 200PS」	2018	81
DBA-JB2XC	「XF 300PS」 「XF 250PS」 「XF 200PS」	2018	9
DBA-JBS2XC	「XF Sportbrake」	2018	140
DBA-J60XB	「F-TYPF Coupe」	2018	47
DBA-J60XB	「F-TYPF Convertible」	2018	10
Total			452