

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2660	Date	May, 18, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>The brazing of the fuel rail end caps is inconsistent and may not provide the design condition so not sealing the fuel rail ends. Fuel vapour and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.</p> <p>Fuel odour may be noticed by the driver and they may also observe liquid fuel if the bonnet is lifted.</p> <p>Should leaking fuel come into contact with a sufficiently hot surface there is an increased risk of fire.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
DBA-LC2XB	「Discovery Sport」	2018	20
DBA-LV2XB	「Range Rover Evoque」	2018	65
DBA-LY2XCB	「Range Rover Velar」	2018	41
Total			126