

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai – 2664	Date	May, 18, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	At temperatures below 0 degrees Celsius where the linkage detaches in recirculation mode, it may not be able to clear condensation / fog from the inside of the front windshield or other windows. Failure to be able to de-mist the interior windows in a timely manner can restrict the driver's field of vision and could lead to an increased risk of an accident.		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-LY3VA	「Range Rover Velar」	2018	147
LDA-LY2NA	「Range Rover Velar」	2018	288
DBA-LY2XCB	「Range Rover Velar」	2018	1
Total			436