

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4265	DATE	May.23.2018
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the electric parking brake (EPB) system of the subject vehicles, due to improper programming of the electronic control unit (ECU) , if a battery is deteriorated, there is a possibility that a voltage reduction during an engine re-start after an idling stop could be judged abnormal. If this were to occur, the warning light will illuminate and the EPB system will become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-AGH30W DBA-AGH35W DBA-GGH30W DBA-GGH35W	[ALPHARD] [VELLFIRE]	2014-2018	35,213	idling stop and start system vehicle
		TOTAL		35,213