

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4267	DATE	May 24 ,2018
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>The subject matter relates to the improper data writing process occurred during the manufacturing process of the medium-duty trucks so that some of the data entered into the body control module do not match with the vehicle specification. Consequently, the systems which include brake light control and air compressor control do not function properly.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FRR90S2 2PG-FRR90T2 2RG-FRR90S1 2RG-FRR90S2	[FORWARD]	2017	14
2PG-FSR90S2 2PG-FSR90T2 2RG-FSR90S2		2017-2018	5
2RG-FTR90U2 2RG-FTR90V2		2017-2018	4
2PG-BRR90T2	[CONDOR]	2018	1
		TOTAL	24