

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4254	DATE	May 28, 2018
MANUFACTURER	KYB Corporation 4-1, Hamamatsu-cho 2-chome, Minato-ku, Tokyo, Japan		
DESCRIPTION OF DEFECT	In an electric circuit of a generator or the like, some of the connector mounting brackets are improperly processed, so that the connectors are damaged and the vibration control characteristics are deteriorated. Therefore, when continued to be used as it is, contact failure may occur at the terminal because of running vibration or the like, the warning light may be turned on because of a generation defect, and in the worst case the engine may stop and may not be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CW5AL	QUON	Sep,29,2017~Mar,2,2018	21
TOTAL			21