

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2666	DATE	31/May/2018
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Due to missing radius implementation on the mould at the beginning of the project by Sub-supplier of the component, strength of the quick connector is insufficient. The corrective action is to replace the bleeder hose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC90]	2016	320
		TOTAL	320