VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2670	DATE	May 31 2018	
MANUFACTURE	FCA US LLC			
	(Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)			
DESCRIPTION OF DEFECT	The alternator diodes on the vehicles concerned may experience a rapid failure. Depending on the alternator failure, the driver will have limited or no detection of the alternator failing, which can result in vehicle shutdown while driving and/or an under hood electrical fire. The root cause was determined to be thermal fatigue in the silicon diode due to a combination of high operating temperatures and cyclical system load conditions, induced by the Electric Hydraulic Power Steering ("EHPS") and else.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-WK36T	Jeep Grand Cherokee	2014	78
		TOTAL	78