

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2672	DATE	June 8, 2017
MANUFACTURE	Automobiles PEUGEOT Automobiles CITROEN (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	1. The positioning of the starter wiring harness may be incorrect. In case of contacting between the wiring harness and an engine support, the wiring harness may damage due to high-amplitude movements of the engine. This situation might eventually cause a short-circuit. The operation involves adding a protector to this wiring harness, and clamping it to distance it from the support. 2. A possible non-compliance of the fuel pipes positioning near an aerodynamic shield could generate friction between the pipe and shield, and eventually cause a fuel leak. The operation involves adding a sheath to the fuel pipes, or in some cases, will need to be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P845G01	PEUGEOT 3008	2016, 2017	618
LDA-P84AH01	PEUGEOT 3008	2016, 2017	232
ABA-B785G01	CITROEN C4 Picasso	2016, 2017	31
ABA-B7875G01	CITROEN C4 Picasso	2016, 2017	116
	TOTAL		997