

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4283	DATE	June 12,2018
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	The tailgate latch was mounted with low strength bolts whose are different from that of genuine parts due to the insufficient part number confirmation when the mounting bolts were supplied to the vehicle manufacturing process. As a result, if use is continued in that state, there is a risk that the bolts may fracture, and may not satisfy the safety regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-B21A	「DAYZ ROOX」	2018	1
		TOTAL	1