

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4 2 7 8	DATE	June 15, 2018
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>In the road roller, since the installation instruction of the traveling hydraulic hose of the hydrostatic continuously variable transmission (HST) is inappropriate, the running hydraulic hose may come into contact with the sharp corner portion of the frame.</p> <p>Therefore, if continued to be used as it is, there is a possibility that the traveling hydraulic hose is broken due to traveling vibration and the like, the hydraulic fluid leaks, in the worst case the hydraulic pressure decreases and the running stops.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「TW504」	2015 — 2018	805
TOTAL			805