VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



| CAMPAIGN No. | 4284 | DATE | June 15 ,2018 | |
|--------------|---|---|---------------|--|
| MANUFACTURER | NIPPON TREX CO., | LTD. | | |
| DEFECT | construction, some some contacts with the bracket Accordingly, if it is contacts. | Regarding the traveling device of the low-bed semi-trailer for heavy construction, some steel wheels are not fixed to the hub properly, because it contacts with the brake drum due to the wrong selection of the steel wheel. Accordingly, if it is continuously used as it is, tire deflects, and there is a risk of running stability is impaired. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|--------------------|---------------------|----------------------|
| PMS441AG | _ | 2014 | 1 |
| PMR439CR | _ | 2014 | 1 |
| PMR440AJ | _ | 2015 | 1 |
| PMR441AE | _ | 2016 | 1 |
| PMR439CV | _ | 2016 | 1 |
| PMR440AL | _ | 2016 | 1 |
| PMR435AF | _ | 2016 | 1 |
| PMB439AC | _ | 2017 | 1 |
| PMR440AM | _ | 2017 | 1 |
| PMR439DA | _ | 2017 | 1 |
| PLR434AD | _ | 2017 | 1 |
| PMR440AN | _ | 2017 | 1 |
| PMR439DB | _ | 2017 | 1 |
| PMR439CY | _ | 2017 | 1 |
| PMR439CZ | _ | 2017 | 1 |
| PMR440AP | _ | 2017 | 1 |
| PMR442AA | _ | 2017 | 1 |
| PLR429AN | _ | 2018 | 1 |
| PMR439CS | _ | 2015 | 1 |
| PMR440AH | _ | 2015 | 2 |
| PMR439CU | _ | 2015 | 1 |
| PMR441AF | _ | 2016 | 1 |
| PMR440AK | _ | 2016 | 1 |
| | | TOTAL | 24 |