

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|--|------|--------------|
| CAMPAIGN No. | GAI-2673 | Date | Jun 20, 2018 |
| MANUFACTURER | Volkswagen (Japanese Importer: Volkswagen Group Japan KK) | | |
| DESCRIPTION OF DEFECT | Due to improper fuse coating material, poor contact by nonconductive material (Zinc Oxide) may cause partial exterior lighting failures including main head light, front fog light, positioning light, license plate light, tail light, rear fog light, brake light, additional brake light, reverse light, and turn signal light. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|----------------------|---------------------|-------------------|
| Unknown | Scirocco 1.4 | MY2009 | 4 |
| | Scirocco 2.0 | | 5 |
| | Golf 1.4 | MY2010 | 2 |
| | Golf 2.0 | | 4 |
| ABA-13CAV | VW Scirocco 1.4 | MY2009-MY2010 | 785 |
| ABA-13CAW | VW Scirocco 2.0T | | 618 |
| ABA-13CCZ | VW Scirocco 2.0T | MY2010-MY2011 | 249 |
| ABA-13CDL | VW Scirocco R20 | MY2010-MY2012 | 421 |
| ABA-1FBUB | VW EOS 3.2 V6 | MY2009 | 31 |
| ABA-1FBWA | VW EOS 2.0T | | 131 |
| ABA-1FCAW | VW EOS 2.0T | | 37 |
| ABA-1KAXX | VW Golf 2.0 GTI/GTX | MY2009 | 1,261 |
| | VW Jetta 2.0T | | 496 |
| | VW Golf Variant 2.0T | | 750 |
| ABA-1KBLG | VW Golf 1.4/125kw | MY2009 | 1,834 |

| | | | |
|------------|-----------------------------|---------------|---------|
| ABA-1KBMY | VW Golf 1.4/103kw | MY2009 | 26 |
| ABA-1KBUBF | VW Golf R32 | | 107 |
| ABA-1KBYD | VW Golf Pirelli 2.0T | | 997 |
| ABA-1KCAV | VW Jetta 1.4/118kw | MY2009-MY2010 | 1,311 |
| | VW Golf 1.4/118kw | | 4,204 |
| | VW Golf Variant 1.4/118kw | | 5,169 |
| ABA-1KCAW | VW Golf Variant 2.0T | MY2009 | 162 |
| ABA-1KCAX | VW Golf 1.4/90kw | MY2009-MY2010 | 9,348 |
| | VW Golf Variant 1.4/90kw | | 2,927 |
| ABA-1KCCZ | VW Golf GTI 2.0T | MY2010-MY2012 | 7,273 |
| | VW Golf Variant 2.0T | | 639 |
| ABA-1KCDL | VW Golf GTI Edition35 | MY2012 | 353 |
| ABA-1KCDLF | VW Golf R20 | MY2010-MY2012 | 1,492 |
| ABA-1TBLG | VW Golf Touran 1.4/125kw | MY2009 | 1,766 |
| ABA-1TBMY | VW Golf Touran 1.4/103kw | | 1,893 |
| ABA-1TCAV | VW ゴルフ Touran 1.4/103kw | MY2010 | 2,460 |
| DBA-13CAV | VW Scirocco 1.4/118kw | MY2011-MY2012 | 701 |
| DBA-1KCAV | VW Golf 1.4/118kw | MY2011-MY2012 | 3,264 |
| | VW Golf Variant 1.4/118kw | | 4,812 |
| DBA-1KCAVK | VW Golf Cabriolet 1.4/118kw | MY2012 | 1,045 |
| DBA-1KCAX | VW Golf 1.4/90kw | MY2010-MY2012 | 19,210 |
| | VW Golf Variant 1.4/90kw | | 6,484 |
| DBA-1KCBZ | VW Golf 1.2/77kw | MY2010-MY2012 | 11,293 |
| | VW Golf Variant 1.2/77kw | MY2012 | 1,365 |
| DBA-1TCAV | VW Golf Touran 1.4/103kw | MY2011-MY2012 | 6,517 |
| | | Total | 101,446 |