

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4290	DATE	June 28, 2018
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to temperature cycling under humid condition. Therefore, during the airbag deployment, the container of inflator may be broken, components may be scattered, causing passengers to be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-DE3AS	Mazda 「DEMIO」	2010	1
DBA-DE3FS		2007- 2014	32
DBA-DE3FS KAI		2012-2013	6
DBA-DE5FS		2007-2010	15
DBA-DEJFS		2011-2013	18
ABF-SKP2T	Mazda 「BONGO」	2012-2014	4
ABF-SKP2V		2014	1
		Total	77