VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2680	DATE	June 29, 2018
MANUFACTURE	Automobiles CITROEN		
	(Japanese Importer :	PEUGEOT CITROËN JAI	PON Co.,Ltd.)
DESCRIPTION OF DEFECT	 The striker on the bonnet may not have sufficient support to prove it with the security for its intended purpose. This can lead to cracking of the bonnet striker over time and could result in an unintentional release of the bonnet. Due to a non-conformity in production a layout of fuel pipe could cause wear due to contact with surrounding components. This may cause a fuel leak. 		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-E3HM01	CITROEN C4 Cactus	2016-2017	648
		TOTAL	648