VEHICLE SAFETY/POLLUSION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4261	DATE	June 29, 2018
MANUFACTURER	Shinmaywa Industries, Ltd.		
DESCRIPTION OF DEFECT	In the axle of the trailer, there is merging shortage of the welding in a part of vehicle because the execution management of the automatic welding machine that produces the axle is insufficient. Therefore when there is the case that a crack occurs on an axle and continues running in a state as is, in the case of the worst, a crack is worse, and there is a threat that an axle is damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TSB182	Semi-trailer	1995	6
TSB183	Semi-trailer	1995	2
TSB210	Semi-trailer	1995	3
TSB220	Semi-trailer	1996~1997	32
TSB237	Semi-trailer	1996~1997	5
TSB240	Semi-trailer	1996~1998	13
TSB256	Semi-trailer	1996	2
		TOTAL	63