

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4262	DATE	June 29,2018
MANUFACTURER	KYB CORPORATION		
DESCRIPTION OF DEFECT	In the axle of the trailer, there is merging shortage of the welding in a part of vehicle because the execution management of the automatic welding machine that produces the axle is insufficient. Therefore when there is the case that a crack occurs on an axle and continues running in a state as is, in the case of the worst, a crack is worse, and there is a threat that an axle is damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ2000C	Semi-trailer	1995	2
PJ2400C	Semi-trailer	1996~1997	5

以下略