

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4292	DATE	July 3. 2018
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	At hydrostatic transmission (HST) in self-propelled reaping and threshing machine (combine harvester), the amount of grease in the cover of emergency operation lever is improperly; the pressure in the cover is increased in use, the lever is pushed and servo spool is pushed. Using in that condition, the sliding resistance of servo spool is increased. It might result in steering or traveling malfunction in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YH460」	2015~2017	285	
	「YH470」	2015~2017	367	
	「YH570」	2015~2017	487	
—	「YH590」	2015~2017	298	
EDR-C114	「AG6100」	2011~2013	369	
	「AG6114」	2011~2013	404	
	「AG7114」	2011~2013	128	
—	「AG6100R」	2014~2017	898	
	「AG6114R」	2014~2017	524	
	「AG7114R」	2014~2017	60	
			TOTAL	3,820