

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2688	DATE	2018/7/5
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain E-/ G-Class and ML, GL, CLS vehicles (212, 463, 166, 218 platforms) with 8-cylinder gasoline engine (M157), the software in the engine control module might not meet the specifications. In this case, OBD-relevant fault codes, that are stored in the fuel control unit system, might not be indicated by the check engine warning lamp (MIL) despite legal requirements. As a result, the customer will not receive an advance warning due to the nature of the failure mechanism.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-218375	CLS63S	2015	35
CBA-218376	CLS63S 4MATIC	2015	29
CBA-218976	CLS63S 4MATIC Shooting Brake	2015	17
CBA-212074	E63	2015	1
CBA-212075	E63S	2015	2
CBA-212076	E63S 4MATIC	2014	1
		2015	6
CBA-212292	E63 4MATIC Wagon	2015	3
ABA-463272	G63 AMG	2013	45
		2014	44
		2015	204
CBA-166874	GL63 4MATIC	2013	4
		2014	15
		2015	28
CBA-166074	ML63 4MATIC	2013	20
		2014	6
		2015	9
		TOTAL	469