

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2692	DATE	July 9 th , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	At the electric auxiliary coolant pump for the turbocharger, when the temperature and pressure inside the pump increase, moisture may form on the circuit board and short circuit may occur, which could lead to smoldering of the plug connection and, in worst case, it can cause vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FR44	BMW 550i	2010 – 2011	113
ABA-SN44	BMW 550i Gran Turismo	2010 – 2011	11
ABA-SP44	BMW 550i xDrive Gran Turismo	2010 – 2011	6
ABA-MU44	BMW 550i Touring	2011	1
ABA-LX44C	BMW 650i Coupe	2011	69
ABA-LZ44	BMW 650i Cabriolet	2011	62
ABA-KA44	BMW 750i	2008 – 2011	166
ABA-KB44	BMW 750Li	2008 – 2011	77
ABA-KB60	BMW 760Li	2010 – 2011	24
DAA-KX44	BMW ActiveHybrid 7	2010 – 2011	303
DAA-KX44L	BMW ActiveHybrid 7L	2010 – 2011	106
ABA-ZV44	BMW X5 xDrive 50i	2010 – 2011	35
ABA-ZV44S		2010 – 2011	11
ABA-GY44	BMW X5 M	2010 – 2011	18
ABA-FG44	BMW X6 xDrive 50i	2008	46
ABA-GZ44	BMW X6 M	2010 – 2011	34
AAA-FH44	BMW ActiveHybrid X6	2010 – 2011	29
ABA-MM16	MINI Clubman Cooper S	2008 – 2009	4
DBA-ZG16	MINI Cooper S Clubman	2010 – 2011	875
ABA-MMJCW	MINI JCW Clubman	2010 – 2011	13
ABA-MF16S	MINI Cooper S	2007 – 2008	2
DBA-SV16		2010 – 2011	1,397
ABA-MFJCW	MINI Cooper S JCW	2010 – 2011	128
DBA-ZP16	MINI Cooper S Convertible	2010 – 2011	175
ABA-MSJCW	MINI JCW Convertible	2010 – 2011	20

DBA-SX16S	MINI Cooper S Coupe	2011	41
ABA-SXJCW	MINI JCW Coupe	2011	4
DBA-ZC16	MINI Cooper S Crossover	2011	2,163
CBA-ZC16A	MINI Cooper S Crossover A4	2010 – 2011	838
DBA-ZC16A		2011	150
		TOTAL	6,921

Note: This recall is to expand the range of affected vehicles to the recall which was announced on 02. December 2011 and 24. January 2012.