

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2694	DATE	July 12 <sup>th</sup> , 2018
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	At the electric auxiliary coolant pump for the turbocharger, when the temperature and pressure inside the pump increase, moisture may form on the circuit board and short circuit may occur, which could lead to smoldering of the plug connection and, in worst case, it can cause vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AM10	B5 Biturbo	2011	29
ABA-BM10	B5 Biturbo Touring	2011	2
ABA-6M10	B6 Biturbo Coupe	2012	1
ABA-CM10	B7 Biturbo Allrad	2011	5
ABA-KM10	B7 Biturbo Long	2009-2011	2
		TOTAL	39

Note: This recall is to expand the range of affected vehicles to the recall which was announced on 02 December 2011.