

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2677	DATE	July 13, 2018
MANUFACTURE	RENAULT SA (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	In the low beam of headlight, the height sensor of auto headlight beam direction control did not set the correctly due to wrong procedure of manufacturing process therefore, auto headlight beam direction control function does not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-RM5M	「LUTECIA R.S.」	2017-2018	2
ABA-RM5M1			5
		TOTAL	7