

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2697	DATE	July. 17. 2018
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The side stand connection can bend, or in an extreme case even break. The side stand connection will be checked for preliminary damage and an additional reinforcement will be installed as the side stand becoming unsafe cannot be ruled out in the case that this fault should occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-G31AA	BMW G310R	2017-2018	746
2BL-G31AA	BMW G310GS	2017-2018	653
		TOTAL	1,399