

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4302	DATE	20-July-2018
MANUFACTURE	KCM Corporation		
DESCRIPTION OF DEFECT	About the component of steering system on shovel loader (wheel loader),there is the possibility that the Hydraulic rubber hose may be removed when input higher pressure on the condition of steering job because of the lack of hose strength. Finally lead to oil leaking , increase the steering force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDP-H88	「ZW100-6」	2017-2018	60	
YDP-H87	「ZW120-6」	2018	1	
TOTAL			61	