

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4303	DATE	July 23,2018
MANUFACTURER	HOWAMACHINERY,LTD.		
DESCRIPTION OF DEFECT	The front wheel supporting section of the motor-sweeper is insufficient in strength. Vibrations generated during travel may lead to cracks in this section. In the worst-case, continuing to operate the sweeper with cracks may result in serious damage to this section and steering force of the front wheel may be heavy by interfering with the front wheel steering chain		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HF64AH	HF64AH	2010 ~2014	41
TOTAL			41