

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4306	DATE	July.26, 2018
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to inadequacies in the application for noise test or errors in writing in the noise test data sheet, the noise label does not contain correct noise test conditions or acceleration noise value and therefore, it does not conform to the technical requirements of the Regulation No. 41.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-MC33	「VTR」 「VTR Type LD」 「VTR-F」	2014～2017	4,488
2BL-NC42	「CB400 SUPER FOUR」 「CB400 SUPER BOLD'OR」	2017～2018	1,680
2BL-SC54	「CB1300 SUPER FOUR」 「CB1300 SUPER BOLD'OR」	2017～2018	724
2BL-RC88	「NC750S」	2016～2018	732
EBL-NC42 2BL-NC54	「CB400 SUPER FOUR」	2016～2018	729
EBL-SC68	「GOLD WING F6C」	2014～2016	229
2BL-SC62	「CB1300P」	2014～2018	222
		TOTAL	8,804