

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-2703	DATE	7 <sup>th</sup> August 2018
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K. )		
DESCRIPTION OF DEFECT	Due to incorrectly sealed electrical circuits in the left-hand switch cube, water may contaminate the component and, as a consequence, the turn signal indicator control switches may not function correctly.		

2BL-H4J765	Street Triple RS	2017	106
	Street Triple R low	2017	55
		TOTAL	161