

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2705	DATE	2018/8/7
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain CLS vehicles (218 platform) with 6-cylinder gasoline engine the installed NOx-sensor type is not specified for this engine and model. Depending on the driving scenario, the onboard diagnosis might not detect that the sensor does not meet the specified characteristics. In this case the exhaust after-treatment might be impaired. This could lead to an exceedance of legal emission limit values.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MBA-218361	CLS400	2016	28
		2017	143
MBA-218961	CLS400 Shooting Brake	2016	9
		2017	36
		TOTAL	216